SAMSUNG

DVD RECEIVER AMP

MM-DS80M

CHANGE NOTES.

1. DVD-PACK Specification is changed .

SERVICE Manual

SUPPLEMENT-1

Supplement to the Service Manual MM-DS80M

This supplement contains change notes differing from the Service Manual MM-DS80M use both this supplement and the Service Manual part number AH68-01383G

DVD RECEIVER AMP



CONTENTS

1. Electrical Parts List

2. Block Diagrams

3. Schematic Diagrams

4. Troubleshooting

Notice !! You can search for the updated part code through ITSELF web site.
URL; http://itself.sec.samsung.co.kr

- Confidential -

ELECTRONICS

This Service Manual is a property of Samsung Electronics Co.,Ltd.
Any unauthorized use of Manual can be punished under applicable international and/or domestic law.

© Samsung Electronics Co.,Ltd. APR. 2004
Printed in Korea
Code no. AH68-01383G-001